Company		Listing Submitted	11/19/2018	Area of state conducts work	
ABC Global Contracting LLC		Phone (810) 533-2416		Coastal (East of I-95): Yes	
32032 28 Mile Road		Fax		Central (West of I-95 and East of I-77): Yes	
Lenox, Michigan 48048-				Mountains (West of I-77): Yes	
		Website abcglobalcontracting.com		Mountains (West of 1-77). Tes	
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/4/2020	Area of state conducts work	
Advanced Environmental Services, Inc.		Phone (336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax (336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438				Mountains (West of I-77): Yes	
		Website advancedenvironmental.com			
Comp		Website advancedenvironmental.com			
•	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	pliance Te		No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
-		esting and Monitoring	No No		No No
Automatic Line Leak Detector Testing:	No	esting and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No No No No No No No No No Vo	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No The state of t	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Se	rvice P	rovider List (All) - Environmen	ital Servic	e Firms Only	
Company		Listing Submitte	d 10/2/2017	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	S
141 S. Market Street Washington, NC 27889		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	s
Washington, No 27000	Website www.aes-nc.com			Mountains (West of I-77): Yes	
Сотр	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		

Soil and Water Testing Lab:	No					
Company			Listing Submitted	10/13/2017	Area of state conducts work	
Apex Engineering, PC	Ph	one (301) 417-0200			Coastal (East of I-95): Yes	i
15850 Crabbs Branch Way Suite 200		Fax (301) 975-0169			Central (West of I-95 and East of I-77): Yes	;
Rockville, Maryland 20855-	Web	site www.apexcos.com			Mountains (West of I-77): Yes	i
Comp	pliance Testing	and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Op	erability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No St	atistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	oill Prevention Equipment Testin	g:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ink Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No O	her:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Eı	nvironmental S	ervice Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes U	ST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes U	ST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes W	aste Disposal and Treatment:		<u>Yes</u>		

Soil and Water Testing Lab:

Oil and Solvent Recycling:

No

Other:

Other:

<u>Yes</u>

<u>Yes</u>

UST Service Provider List (All) - Environmental Service Firms	Only
------------------------------------	------------------------------------	------

Company		Listing Submitted	1/2/2018	Area of state conducts work	
Applied Science & Engineering, LLC	F	Phone (813) 207-5061		Coastal (East of I-95): Yes	
550 N. Reo Street		Fax (813) 288-1550		Central (West of I-95 and East of I-77): Yes	
Tampa, FL 33609		(010) 200 1000		Mountains (West of I-77): Yes	
	We	bsite		Mountains (West of 1-77). Tes	
Comp	liance Testir	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	vironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Blue Ridge Geological Services, Inc.	F	Phone (336) 382-6849		Coastal (East of I-95): Yes	
7356 Belmont Drive				· · · · · · · · · · · · · · · · · · ·	
		Fax		Central (West of I-95 and Fast of I-77): Yes	
Trinity, NC 27370		Fax		Central (West of I-95 and East of I-77): Yes	
	We	Fax bsite www.blueridgegeo.com		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Trinity, NC 27370					
Trinity, NC 27370	oliance Testir	bsite www.blueridgegeo.com	No	Mountains (West of I-77): Yes	No
Trinity, NC 27370	oliance Testir	bsite www.blueridgegeo.com ng and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing:	No No	bsite www.blueridgegeo.com ag and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No No	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No No	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No No	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No <u>Yes</u>	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No <u>Yes</u> No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	bsite www.blueridgegeo.com ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No <u>Yes</u> No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	bsite www.blueridgegeo.com ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No <u>Yes</u> No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No <u>Yes</u> No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er	No Ves	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No Yes No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Ves nvironmental Yes Yes	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No Yes No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Trinity, NC 27370 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes ovironmental Yes Yes Yes	bsite www.blueridgegeo.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No Yes No No Yes No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Se	ervice	e Provider List (All) - Environmenta	al Service	e Firms Only	
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Bunnell-Lammons Engineering Inc.		Phone (828) 277-0100		Coastal (East of I-95): No	
130 Oval Road		Fax (828) 277-0110		Central (West of I-95 and East of I-77): Yes	
Suite 200 Arden, NC 28704		Website www.blecorp.com		Mountains (West of I-77): Yes	
Comp	oliance	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironn	nental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other: Trust Fund P	rojects		
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC		Phone (919) 757-7901		Coastal (East of I-95): Yes	
8005 Clear Brook Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615		Website CapeLookoutEnv.com		Mountains (West of I-77): Yes	
Comr	nliance	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Loan Botoston Equipment Operability Officer.	110	Con marinal Entiting hispotations.	140	LIOT BULL (O	INO

Soil and Water Testing Lab:

Line Tightness Testing:

Leak Detection Monitoring Services:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

No

<u>Yes</u>

<u>Yes</u>

<u>Yes</u>

No

Other:

Other:

UST Compliance Consultants:

Waste Disposal and Treatment:

UST Equipment Verification:

Environmental Service Firms

No

No

UST Piping/Sump Installation:

UST System Removal:

Other:

<u>Yes</u>

Yes

Company		Listing Submi	itted 11/14/2018	Area of state conducts work	
Carbon Fuel Services, LLC	P	hone (704) 419-9939		Coastal (East of I-95): Yes	
301 E Main Street	_	Fax		Central (West of I-95 and East of I-77): Yes	
Cherryville, NC 28021-		I dx			
	We	osite <u>www.carbonfuelservices.com</u>		Mountains (West of I-77): Yes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No l	JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No l	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (Other: Diesel Fuel Compliance Labora	atory Testing	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmental	Service Firms		Other: Diesel Fuel Polishing, Filtration, and Recovery	Services
Emergency Cleanup - Spill/Release:	No l	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No l	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No \	Vaste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No (Other: Diesel Fuel Additives and Tank Clea	aning Agents		
Soil and Water Testing Lab:	No				
Company		Listing Submi	itted 1/3/2020	Area of state conducts work	
CATLIN Engineers and Scientists	Р	hone (910) 452-5861		Coastal (East of I-95): Yes	
220 Old Dairy Road					
Miles in others NC 2040E		Fax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28405		Fax		Central (West of I-95 and East of I-77): Yes	
wilmington, NC 28405	We	Fax bsite www.CatlinUSA.com		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
-					
-	oliance Testin	bsite www.CatlinUSA.com	No	Mountains (West of I-77): No	No
Comp	No (psite www.CatlinUSA.com g and Monitoring	No No	Mountains (West of I-77): No UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	No (No (S	posite www.CatlinUSA.com g and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:	No S	posite www.CatlinUSA.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No S No S No S No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S	g and Monitoring Describe The Very Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	g and Monitoring Diverfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S	g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No Yes No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitted	8/18/2020	Area of state conducts work	
Charles Broadfoot & Associates, Inc.		Phone (910) 574-4748		Coastal (East of I-95): Yes	
PO Box 53730		Fax 253-681-05		Central (West of I-95 and East of I-77): Yes	
1827 Morganton Rd.		1 ux 200 001 00			
Fayetteville, NC 28305	V	Vebsite <u>www.ustcomonline.com</u>		Mountains (West of I-77): Yes	
Comp	pliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Off	Overfill Prevention Equipment Operability Check:	Off	Dispenser Meter Repair/Calibration:	Off
Containment Sump Testing:	Off	Statistical Iventory Reconciliation Services:	Off	Leak Detection Equipment Installation Servicing:	Off
Corrosion Protection Design Experts:	Off	Spill Prevention Equipment Testing:	Off	Spill Bucket Installation Repair:	Off
Corrosion Protection System Repairs:	Off	Tank Tightness Testing:	Off	UST Equipment Installation - Other:	Off
Corrosion Protection System Testing:	Off	UST Internal Inspections (Integrity Assessments):	Off	UST Equipment Repair:	Off
Leak Detection Equipment Operability Check:	Off	UST Internal Lining Inspections:	Off	UST System Installation - Complete Systems:	Off
Leak Detection Monitoring Services:	Off	Other:		UST Piping/Sump Installation:	Off
Line Tightness Testing:	Off			UST System Removal:	Off
Ei	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Off	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Off	UST Equipment Verification:	Off		
Environmental Engineer/Geologist Soil and GW Cleanu	Off	Waste Disposal and Treatment:	Off		
Oil and Solvent Recycling:	Off	Other:			
Soil and Water Testing Lab:	Off				
Company		Listing Submitted	10/9/2017	Area of state conducts work	
Christopher Dunlap, P.G.		Phone (828) 505-6301		Coastal (East of I-95): No	
166 Michigan Avenue		For		Central (West of I-95 and East of I-77): Yes	
Asheville, NC 28806		Fax			
Asheville, NO 20000		Fax			
Asheville, NO 20000	W	Vebsite		Mountains (West of I-77): Yes	
		Vebsite	No	Mountains (West of I-77): Yes	No
Comp	pliance Test	Vebsite ting and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	pliance Test No	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Test No No	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Test No No No	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Test No No No No	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No N	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Vebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

LICT C	!	Dravidan Liet (All) Environment	al Camila	a Firma Only	
	ervice	Provider List (All) - Environment		•	
Company		Listing Submitted	6/17/2020	Area of state conducts work	
Clark Group dba Clark Environmental Service	s, PC	Phone (910) 392-5555		Coastal (East of I-95): Yes	3
P.O. Box 10136		Fax (910) 392-5552		Central (West of I-95 and East of I-77): Yes	;
Wilmington, NC 28404		Website www.clarkgroup.us		Mountains (West of I-77): Yes	;
Com	pliance [*]	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironm	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Clean	u <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	10/12/2017	Area of state conducts work	
Cobb Environmental & Technical Services, In	c.	Phone (662) 841-0995		Coastal (East of I-95): Yes	;
P. O. Box 1602, Tupelo, MS 38802		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	3
871 South Green Street		, ,		Mountains (West of I-77): Yes	
Tupelo, MS 38804		Website www.cobbenv.com		mountaino (trost of 177).	•
Com	pliance [*]	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironm	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
			l l		

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu No

No

Other:

Waste Disposal and Treatment:

No

Company		Listing Subm	nitted 11/15/2018	Area of state conducts work	
CROMPCO, LLC	F	Phone (800) 646-3161		Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621		Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462		(010) 270 7021		Mountains (West of I-77): Yes	
	We	ebsite <u>www.crompco.com</u>		Modificants (West of 1-77). Tes	
Comp	pliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments)	: No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Subm	nitted 8/1/2019	Area of state conducts work	
D.H. Griffin Wrecking, Inc.	F	Phone (336) 389-3647		Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax (336) 389-3647		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407		(000) 000 0011		Mountains (West of I-77): Yes	
	We	ebsite <u>www.dhgriffin.com</u>		Mountains (West of 1-77). Tes	
Comp	pliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments)	: No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
				UST System Removal:	<u>Yes</u>
Line Tightness Testing:	No				
		Service Firms		Other:	
	nvironmental	Service Firms UST Compliance Consultants:	No	Other:	
E	nvironmental <u>Yes</u>		No No	Other:	
Emergency Cleanup - Spill/Release:	nvironmental Yes No	UST Compliance Consultants:		Other:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	nvironmental Yes No No	UST Compliance Consultants: UST Equipment Verification:	No	Other:	

UST Service Provider List (All) - Enviro	nmental Service Firm	s Only
Listing S	Submitted 6/20/2018	Area of st

Company		Listing Subn	nitted 6/20/2018	Area of state conducts work	
DAVENPORT		Phone (910) 251-8912		Coastal (East of I-95): Yes	
3722 Shipyard Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Suite E				Mountains (West of I-77): Yes	
Wilmington, NC 28412	V	Website http://www.davenportworld.com/		modificants (West of 177). Tes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Subn	nitted 10/4/2018	Area of state conducts work	
Company Fast Carolina Petroleum Services Inc		Phone (252) 339-3655	nitted 10/4/2018	Area of state conducts work Coastal (Fast of I-95): Yes	
East Carolina Petroleum Services Inc PO Box 1923		Phone (252) 339-3655	nitted 10/4/2018	Coastal (East of I-95): Yes	
East Carolina Petroleum Services Inc			nitted 10/4/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
East Carolina Petroleum Services Inc PO Box 1923	V	Phone (252) 339-3655	nitted 10/4/2018	Coastal (East of I-95): Yes	
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909		Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com	nitted 10/4/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp	pliance Tes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp	oliance Tes Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Tes Yes Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	yes Yes Yes No Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No Yes Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments)	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No Yes Yes Yes Yes Yes Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections: Other:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections: Other:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes Yos No No	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes Yos No No	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes No No No Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
East Carolina Petroleum Services Inc PO Box 1923 510 W Broad Street Elizabeth City, NC 27909 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes Yes No Yes Yes Yes Yes Yes Yes Yes You	Phone (252) 339-3655 Fax (252) 331-2754 Vebsite ecpetro.com ting and Monitoring Overfill Prevention Equipment Operability Check Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes No Yes No No No Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company		Listing Submitted	5/26/2020	Area of state conducts work	
East Coast Environmental PA		Phone (919) 772-0268		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27603		Tux		Mountains (West of I-77): No	
	V	Website <u>eastcoastenv.com</u>		Mountains (west of 1-77): No	
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Ei	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/15/2018	Area of state conducts work	
EMS Environmental, Inc.		Phone (919) 596-0470		Coastal (East of I-95): Yes	
117 South Hoover Road		Fax (919) 596-0578		Central (West of I-95 and East of I-77): Yes	
Durham, NC 27703		(010) 000 0010			
	V	Website www.emsenv.com		Mountains (West of I-77): Yes	
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:					
Containment Sump Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Corrosion Protection Design Experts:					
	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No Tronment No Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Tronment No Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company				10/18/2017	Area of state conducts work	
Enviro Consulting		Phone (704) 721-0101			Coastal (East of I-95): Yes	
531 Pitts School Road NW		Fax (704) 721-0102			Central (West of I-95 and East of I-77): Yes	
Suite D		1 dx (704) 721-0102				
Concord, NC 28027	V	Website www.envirocorp.net			Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Opera	ability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Se	ervices:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:		<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity A	ssessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	UST Lining Insta	llation	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company		Li	sting Submitted	7/30/2020	Area of state conducts work	
Environmental Contracting & Consulting Serv	ices, P	Phone (757) 912-2276			Coastal (East of I-95): Yes	
10 3rd Avenue	,	Fax			Central (West of I-95 and East of I-77): No	
Southern Shores, NC 27949		T un				
	V	Vebsite			Mountains (West of I-77): No	
Comp	elienes T					
	pilance Les	ting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No No	ting and Monitoring Overfill Prevention Equipment Opera	ability Check:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:				No No		No No
	No	Overfill Prevention Equipment Opera	ervices:		Dispenser Meter Repair/Calibration:	
Containment Sump Testing:	No No	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se	ervices:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing:	ervices:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing:	ervices:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A	ervices:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections:	ervices:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections:	ervices:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections: Other:	Assessments):	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Vo	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections: Other:	ervices: Assessments):	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No No Vo revironment Yes Yes	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections: Other:	Assessments):	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No No No No No No No No Vo revironment Yes Yes	Overfill Prevention Equipment Opera Statistical Iventory Reconciliation Se Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Assessments):	No No No No Yes Yes Yes	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		Listi	ng Submitted	8/4/2020	Area of state conducts work	
	Phone	(864) 370-0637			Coastal (East of I-95): Yes	;
	Fax	(864) 752-0948			Central (West of I-95 and East of I-77): Yes	;
					Mountains (West of I-77): Yes	;
٧	Vebsite	www.elabsinc.net			, , , ,	
pliance Tes	ting and	l Monitoring			UST Equipmment Service Contractors	
<u>Yes</u>	Overfill	Prevention Equipment Operabil	ity Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
<u>Yes</u>	Statistic	cal Iventory Reconciliation Servi	ces:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
No	Spill Pr	evention Equipment Testing:		<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
<u>Yes</u>	Tank Ti	ightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
<u>Yes</u>	UST Inf	ternal Inspections (Integrity Asse	essments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
<u>Yes</u>	UST Inf	ternal Lining Inspections:		<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
<u>Yes</u>	Other:				UST Piping/Sump Installation:	<u>Yes</u>
<u>Yes</u>					UST System Removal:	<u>Yes</u>
nvironment	al Servi	ce Firms			Other:	
No	UST Co	ompliance Consultants:		Yes		
No				No No		
ı No	Waste	Disposal and Treatment:		No		
No	Other:	•				
No						
		Listi	ng Submitted	5/7/2018	Area of state conducts work	
	Phone			0,1,2010		
		, ,				
	Fax	(919) 855-9083				5
1	Nebsite	www.erllc.com			Mountains (West of I-77): No	
nlianco Tos	ting and	Monitoring			LIST Equipment Service Contractors	
			ity Chaole	No	· · ·	No
					· · · · · · · · · · · · · · · · · · ·	No
			ces.			No No
		-				No
		-	ocemonte):			No
			essinents).			No
		terrial Elling Hispections.		140		No
	Othor.					<u>Yes</u>
110						<u>100</u> DIATION
	-10				TEME	
<u>Yes</u>	UST Co	ompliance Consultants:		Yes		
<u>Yes</u> No	UST Co	ompliance Consultants: quipment Verification:		No		
Yes No I No	UST Co UST Ec	ompliance Consultants:		No <u>Yes</u>		
<u>Yes</u> No	UST Co	ompliance Consultants: quipment Verification:	REMEDIA	No <u>Yes</u>		
	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Website Diance Testing and Yes Overfill Yes Statistic No Spill Pr Yes Tank T Yes UST In Yes Other: Yes Other: Yes Other: Yes Other: No UST Co No UST Eco No UST Eco No Other: No Other: No Other: No Other: No Overfill No Spill Pr No Tank T No UST In No Other: No Other: No Other: No UST In No Other: No Othe	Phone (864) 370-0637 Fax (864) 752-0948 Website www.elabsinc.net Diance Testing and Monitoring Yes Overfill Prevention Equipment Operabil Yes Statistical Iventory Reconciliation Serving No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assets UST Internal Lining Inspections: Yes Other: Yes Other: Yes Other: Yes Invironmental Service Firms No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: No Other: No Other: No Other: No Other: No Overfill Prevention Equipment Operabil No Statistical Iventory Reconciliation Serving No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assets No UST Internal Lining Inspections: No Other:	Website www.elabsinc.net Diliance Testing and Monitoring Yes Overfill Prevention Equipment Operability Check: Yes Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes Other: Yes Other: Yes Other: Yes No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: No Phone (919) 855-9082 Fax (919) 855-9083 Website www.erllc.com Diliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Phone (864) 370-0637 Fax (864) 752-0948 Website www.elabsinc.net Diance Testing and Monitoring Yes Overfill Prevention Equipment Operability Check: Yes Yes Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: Yes Yes Tank Tightness Testing: Yes Yes UST Internal Inspections (Integrity Assessments): Yes Yes Other: Yes Other: Yes No UST Compliance Consultants: Yes No UST Equipment Verification: No No Other: No Listing Submitted 5/7/2018 Phone (919) 855-9082 Fax (919) 855-9083 Website www.erllc.com Diance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No No UST Internal Inspections (Integrity Assessments): No No UST Internal Inspections (Integrity Assessments): No No UST Internal Inspections: No No Other:	Phone (864) 370-0637 Fax (864) 752-0948 Website www.elabsinc.net Website www.elabsinc.net Dilance Testing and Monitoring Wes Overfill Prevention Equipment Operability Check: Yes Statistical Ventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Statistical Ventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Statistical Ventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Spill Bucket Installation Repair: UST Equipment Installation Servicing: Spill Bucket Installation Complete Systems: UST Equipment Repair: UST System Installation - Other: UST Equipment Repair: UST System Removal: Other: Ves UST Compliance Consultants: Yes UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: Other: No UST Compliance Consultants: Yes UST System Removal: Other: No UST Equipment Venfication: No No Waste Disposal and Treatment: No Other: No Other: Listing Submitted 5/7/2018 Area of state conducts work Phone (919) 855-9082 Castal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Dispenser Meter Repair/Calibration: UST System Removal: Other: Dispenser Meter Repair/Calibration: UST Equipment Servicing: No UST Equipment Servicing: No UST Equipment Testing: No UST Equipment Installation - Other: UST Equipment Installation - Other: UST Equipment Installation - Other: UST Equipment Repair: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Equipment Repair: UST Equipment Servicing: Spill Bucket Installation - Other: UST System Removal: UST System Installation: UST System Removal: UST System Removal:

UST Service Provider List (All) - Environme	ental Se	ervice Fi	rms Only
Lioting Cubmit	4404 11/16	E/2019	Aron of ot

Company		Listing Submitte	ed 11/15/2018	Area of state conducts work	
EnviroTrac Ltd.		Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27410				Mountains (West of I-77): Yes	
	W	ebsite www.envirotrac.com		(rroce c. 1 11).	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	l Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitte	ed 7/30/2020	Area of state conducts work	
Envirovation Geologic Consulting and Mappin	ng, PC	Phone (828) 407-0613		Coastal (East of I-95): No	
719-A Greenway Rd		E.		Central (West of LOE and East of L77), Voc	
PO Box 3425		Fax		Central (West of 1-95 and East of 1-77). Tes	
Page NC 20607				Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Boone, NC 28607	W	ebsite https://envirovationconsulting.com/		Mountains (West of I-77): Yes	
		ebsite https://envirovationconsulting.com/	No	Mountains (West of I-77): Yes	No
Сотр	pliance Testi	ebsite https://envirovationconsulting.com/ ing and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Comp Automatic Line Leak Detector Testing:	pliance Testi No	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Testi No No	ebsite https://envirovationconsulting.com/ ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Testi No No No	ebsite https://envirovationconsulting.com/ ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Testi No No No No	ebsite https://envirovationconsulting.com/ ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Testi No No No No No	ebsite https://envirovationconsulting.com/ ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Testi No	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Testi No	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	ebsite https://envirovationconsulting.com/ Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

USISE	ervice P	rovider List (All) - Environment	ai Service	e Firms Only	
Company		Listing Submitted	11/16/2018	Area of state conducts work	
Evo Corporation		Phone (336) 725-5844		Coastal (East of I-95): Yes	S
1703 Vargrave Street		Fax (336) 725-6244	Central (West of I-95 and East of I-77): Yes	s	
Winston-Salem, NC 27107		•		Mountains (West of I-77): Yes	s
	V	Vebsite www.evocorp.net		meaname (creek error).	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Eı	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/29/2020	Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800		Coastal (East of I-95): Yes	S
625 Huntsman Court		Fax (704) 853-3949		Central (West of I-95 and East of I-77): Yes	s
Gastonia, NC 28054	v	Valacita		Mountains (West of I-77): Yes	s
		Vebsite <u>www.excelengr.com</u>			
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Elife Fightinese Feeting.					
	nvironment	al Service Firms		Other:	
	nvironment No	al Service Firms UST Compliance Consultants:	Yes	Other:	
Eı			Yes No	Other:	

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

Waste Disposal and Treatment:

Other:

No

Company			Listing Submitted	11/9/2018	Area of state conducts work	
Geo-Hydro Engineers, Inc.		Phone ((704) 837-7174		Coastal (East of I-95): Yes	
2748 Interstate Street		Fax	•		Central (West of I-95 and East of I-77): Yes	
Suite A					Mountains (West of I-77): Yes	
Charlotte, NC 28208	W	Vebsite <u>v</u>	www.geohydro.com		Wouldains (West of 1-77). Tes	
Comp	pliance Testi	ing and N	lonitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Pr	evention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical	Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Preve	ention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tigh	tness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Inter	nal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Inter	nal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service	Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Com	pliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equi	pment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes_	Waste Dis	sposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	11/14/2018	Area of state conducts work	
Geological Resources, Inc.		Phone ((704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax ((704) 845-4012		Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28110					Mountains (West of I-77): Yes	
	W	Vebsite <u>v</u>	www.geologicalresourcesinc.com		,	
Comp	pliance Testi	ing and N	lonitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:						
Containment Sump Testing:	No	Overfill Pr	evention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Commont Comp Tooming.	No No		evention Equipment Operability Check: Iventory Reconciliation Services:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Corrosion Protection Design Experts:		Statistical				
	No	Statistical Spill Preve Tank Tigh	Iventory Reconciliation Services: ention Equipment Testing: tness Testing:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No	Statistical Spill Preve Tank Tigh UST Intern	Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessments):	No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No	Statistical Spill Preve Tank Tigh UST Intern UST Intern	Iventory Reconciliation Services: ention Equipment Testing: tness Testing:	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No	Statistical Spill Preve Tank Tigh UST Intern	Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessments):	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No	Statistical Spill Preve Tank Tigh UST Intern UST Intern	Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessments):	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No	Statistical Spill Preve Tank Tigh UST Interi UST Interi Other:	Iventory Reconciliation Services: ention Equipment Testing: thess Testing: nal Inspections (Integrity Assessments): nal Lining Inspections:	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No	Statistical Spill Preve Tank Tigh UST Interi UST Interi Other:	Iventory Reconciliation Services: ention Equipment Testing: thess Testing: nal Inspections (Integrity Assessments): nal Lining Inspections:	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Statistical Spill Preve Tank Tigh UST Interi UST Interi Other: al Service UST Com	Iventory Reconciliation Services: ention Equipment Testing: tness Testing: nal Inspections (Integrity Assessments): nal Lining Inspections:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No No No No No No No No Trionmenta Yes Yes	Statistical Spill Preve Tank Tigh UST Interi UST Interi Other: al Service UST Com UST Equi	Iventory Reconciliation Services: ention Equipment Testing: thress Testing: nal Inspections (Integrity Assessments): nal Lining Inspections: Firms pliance Consultants:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No voironmenta Yes Yes	Statistical Spill Preve Tank Tigh UST Interi UST Interi Other: al Service UST Com UST Equi	Iventory Reconciliation Services: ention Equipment Testing: thress Testing: nal Inspections (Integrity Assessments): nal Lining Inspections: Firms pliance Consultants: pment Verification:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitte	ed 11/29/2018	Area of state conducts work	
GREENWOOD APPLIED SERVICES LLC		Phone (252) 398-6022		Coastal (East of I-95): Yes	
P.O. BOX 238		Fax (252) 356-2208		Central (West of I-95 and East of I-77): No	
COLERAIN, NC 27924				Mountains (West of I-77): No	
		Website www.greenwoodapplied.com		mountains (West of 1-77). No	
Comp	pliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Landfarm Soil Disposal, MMPE,AFVR, W	ell Drilling		
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 1/15/2019	Area of state conducts work	
		Listing Submitte	1/13/2019	Area of state conducts work	
Henry Nemargut Engineering Services		Phone (336) 316-0452	1/13/2019	Coastal (East of I-95): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street			1/13/2019	Coastal (East of I-95): Yes	
Henry Nemargut Engineering Services		Phone (336) 316-0452 Fax (910) 762-3284	1/13/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street		Phone (336) 316-0452	1/13/2019	Coastal (East of I-95): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403		Phone (336) 316-0452 Fax (910) 762-3284	1/13/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403		Phone (336) 316-0452 Fax (910) 762-3284 Website	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp	pliance Te	Phone (336) 316-0452		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Compa	pliance Te No	Phone (336) 316-0452 Fax (910) 762-3284 Website sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Te No No	Phone (336) 316-0452 Fax (910) 762-3284 Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Engergency Cleanup - Spill/Release:	No N	Phone (336) 316-0452 Fax (910) 762-3284 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Other:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 316-0452 Fax (910) 762-3284 Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company		Listing Submitted	11/14/2018	Area of state conducts work	
Highlands Environmental Solutions, Inc.		Phone (919) 848-3155		Coastal (East of I-95): Yes	
8410-D Falls of Neuse Road		Fax (919) 848-4265		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615		(010) 010 1200		Mountains (West of I-77): Yes	
	We	ebsite <u>www.HESfast.com</u>		Mountains (west of 1-77): Tes	
Comp	pliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/14/2020	Area of state conducts work	
INENCO, INC.		Phone (704) 662-8192		Coastal (East of I-95): No	
132 W STATESVILLE AVE		Fax (704) 662-8194		Central (West of I-95 and East of I-77): Yes	
MOORESVILLE, NC 28115		1 dx (704) 002-0134			
	W€	ebsite		Mountains (West of I-77): Yes	
Comp					
	oliance Testii	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		ng and Monitoring Overfill Prevention Equipment Operability Check:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:	No		No No		No No
	No No	Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Containment Sump Testing:	No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No Vo nvironmental No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Se	ervice	Provider List (All) - Environme	ntal Servic	e Firms Only	
Company		Listing Submitte		Area of state conducts work	
Labrador Environmental Consultants, P.C. (ea	astern	Phone (252) 809-9130		Coastal (East of I-95): Yes	1
1450 Johnson Drive Williamston, NC 27892		Fax		Central (West of I-95 and East of I-77): Yes	
		Website		Mountains (West of I-77): Yes	i
Com	pliance ⁻	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironm	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: UST remo	val/closure		
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 8/18/2020	Area of state conducts work	
Law Petroleum, Inc.		Phone (704) 573-3535		Coastal (East of I-95): Yes	i
11025 Arlington Church Road Charlotte, NC 28227		Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes	;
Chanotte, NC 20221		Website		Mountains (West of I-77): Yes	;
Com	pliance ⁻	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	<u>res</u> Yes	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	<u>res</u> Yes	UST Internal Inspections (Integrity Assessments):	<u>res</u> Yes	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	Yes
Loan Dotoblon Equipmont Operability Official.	163	Co. Internal Enling Inopositions.	163	COT Cyclem motaliation Complete Cyclems.	163

Soil and Water Testing Lab:

Line Tightness Testing:

Leak Detection Monitoring Services:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu No

Other:

Other:

UST Compliance Consultants:

Waste Disposal and Treatment:

UST Equipment Verification:

Environmental Service Firms

<u>Yes</u>

<u>Yes</u>

<u>Yes</u>

No

No

No

<u>Yes</u>

<u>Yes</u>

UST Piping/Sump Installation:

UST System Removal:

Other:

<u>Yes</u>

<u>Yes</u>

Company		Listing Submitted	d 11/19/2018	Area of state conducts work	
Martin & Slagle Geo Sciences, P.A.	Phon	ie (828) 669-3929		Coastal (East of I-95): No	
P.O. Box 1023	Fa	(828) 669-5289		Central (West of I-95 and East of I-77): Yes	
24 Lookout Terrace		(===)		Mountains (West of I-77): Yes	
Black Mountain, NC 28711	Websit	e <u>martinandslagle.com</u>		moditalits (West 61177). 163	
Comp	oliance Testing ar	nd Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Over	fill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Statis	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank	Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Othe	r:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Eı	nvironmental Ser	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes UST	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes Wast	e Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Othe	r:			
Soil and Water Testing Lab:	No				
Company		Linda O Lader			
Company		Listing Submitted	d 11/14/2018	Area of state conducts work	
McCallum PC	Phon		d 11/14/2018	Coastal (East of I-95): Yes	
McCallum PC 1808 Hayward Avenue	Phon Fa	e (757) 420-2520	d 11/14/2018		
McCallum PC	Fa	ie (757) 420-2520 ix (757) 424-2874	d 11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
McCallum PC 1808 Hayward Avenue	_	ne (757) 420-2520 nx (757) 424-2874	d 11/14/2018	Coastal (East of I-95): Yes	
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320	Fa	e (757) 420-2520 (757) 424-2874 e www.mccallumtestinglabs.com	d 11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320	Fa Websit pliance Testing an	e (757) 420-2520 (757) 424-2874 e www.mccallumtestinglabs.com	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comp	Website pliance Testing as No Over	te (757) 420-2520 ax (757) 424-2874 e www.mccallumtestinglabs.com and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparing Line Leak Detector Testing:	Websit Poliance Testing an No Overi No Statis	te (757) 420-2520 tx (757) 424-2874 e www.mccallumtestinglabs.com nd Monitoring fill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Websit Pliance Testing and No Overl No Statis No Spill No Tank	e (757) 420-2520 (757) 424-2874 e www.mccallumtestinglabs.com Ind Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparing Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Website pliance Testing and No Overlow Statis No Spill No Tank No UST	e (757) 420-2520 (757) 424-2874 e www.mccallumtestinglabs.com Ind Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Website pliance Testing and No Overlow Statis No Spill No Tank No UST	e (757) 420-2520 (757) 424-2874 e www.mccallumtestinglabs.com Ind Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Website pliance Testing and No Over No Statis No Spill No Tank No UST No UST No Other	te (757) 420-2520 ax (757) 424-2874 e www.mccallumtestinglabs.com and Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Website pliance Testing and No Over No Statis No Spill No Tank No UST No UST	te (757) 420-2520 ax (757) 424-2874 e www.mccallumtestinglabs.com and Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison of the Comparison	Website pliance Testing and No Over No Statis No Spill No Tank No UST No UST No Other	e www.mccallumtestinglabs.com md Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison of the Comparison	Website pliance Testing and No Over No Statis No Spill No Tank No UST No UST No Other No Othe	e www.mccallumtestinglabs.com md Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison of the Comparison of the Comparison of the Comparison of the Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Website Poliance Testing and No Over No Statis No Spill No Tank No UST No UST No Other No No UST No Other No UST No Other No UST No Other No UST No UST No Other No UST	te (757) 420-2520 tx (757) 424-2874 e www.mccallumtestinglabs.com fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	Website Diance Testing and No Over No Statis No Spill No Tank No UST No UST No Other No No UST No Other No UST Yes UST	e www.mccallumtestinglabs.com nd Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r: vice Firms Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
McCallum PC 1808 Hayward Avenue Chesapeake, VA 23320 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Website Website Pliance Testing and No Overland No Statist No Spill No Tank No UST No UST No Other No No UST Yes UST	e www.mccallumtestinglabs.com nd Monitoring fill Prevention Equipment Operability Check: stical Iventory Reconciliation Services: Prevention Equipment Testing: Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: r: vice Firms Compliance Consultants: Equipment Verification: te Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

LIST Se	rvice	Provider List (All) - Environment	al Service	e Firms Only			
Company	SI VICE	Listing Submitted	1/3/2020	Area of state conducts work			
MGF Environmental, PLLC		Phone (904) 814-3680		Coastal (East of I-95): No			
288 Gap Creek Rd.		Fax		Central (West of I-95 and East of I-77): Yes			
Fletcher, NC 28732		I dx					
		Website http://www.mgfenvironmental.com		Mountains (West of I-77): Yes	5		
Comp	pliance Te	esting and Monitoring		UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
E	nvironme	ntal Service Firms		Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company		Listing Submitted	11/13/2018	Area of state conducts work			
Mineral Springs Environmental		Phone (919) 266-8186		Coastal (East of I-95): Yes	S		
4600 Mineral Springs Lane		Fax		Central (West of I-95 and East of I-77): Yes	S		
Raleigh, NC 27616		Mark at a		Mountains (West of I-77): Yes	S		
		Website					
Comp	pliance Te	esting and Monitoring		UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
	nvironmo	ntal Service Firms		Other:			
Ei	iivii oiiiiie	illai Seivice i illiis					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
			No No				

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

Other:

Waste Disposal and Treatment:

No

UST S	Service	Provid	ler List (All) - En	vironment	al Service	e Firms Only	
Company			\ /	sting Submitted		Area of state conducts work	
NC PETROLEUM & CONVENIENCE MARKE	TERS	Phone	(919) 782-4411			Coastal (East of I-95): Yes	s
7300 GLENWOOD AVE.		Fax	(919) 872-4414			Central (West of I-95 and East of I-77): Yes	s
RALEIGH, NC 27612			(/ -			Mountains (West of I-77): Yes	
		Website	WWW.NCPCM.ORG			mountains (West of 177). Tec	
Со	mpliance T	esting and	d Monitoring			UST Equipmment Service Contractors	,
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Opera	ability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statisti	ical Iventory Reconciliation Se	rvices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pr	revention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank T	ightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST In	nternal Inspections (Integrity A	ssessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST In	ternal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	No
	Environme	ental Servi	ce Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST C	ompliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST E	quipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Clea	anu No	Waste	Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:		UST ENGINE	ERING		
Soil and Water Testing Lab:	No						
Company			Lis	sting Submitted	7/30/2020	Area of state conducts work	
Nova Group GBC		Phone	(704) 258-5196			Coastal (East of I-95): Yes	s
442 South Main St		Fax				Central (West of I-95 and East of I-77): Yes	S
Suite # 7						Mountains (West of I-77): Yes	
Davidson, NC 28036		Website	https://www.novagroupg	bc.com/		mountains (west of 177).	•
Co	mpliance T	esting and	d Monitoring			UST Equipmment Service Contractors	1
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Opera	ability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statisti	ical Iventory Reconciliation Se	rvices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pr	revention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank T	ightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST In	nternal Inspections (Integrity A	ssessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST In	nternal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Look Detection Manitorina Compiess.	No	Other:	Environmen	tal compliance insp	ections	UST Piping/Sump Installation:	No
Leak Detection Monitoring Services:							
Line Tightness Testing:	No					UST System Removal:	No

Soil and Water Testing Lab:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

<u>Yes</u>

No

No

<u>Yes</u>

No

No

due diligence

UST Compliance Consultants:

Waste Disposal and Treatment:

UST Equipment Verification:

Other:

UST Service Provider List (All) - Environmental Service Firms Only	
--	--

Company		Listing Su	ibmitted 7/30/2020	Area of state conducts work	
Peak Hydrogeologic, PLLC	Ph	one (828) 817-5209		Coastal (East of I-95): No	
470 Hogback Mountain Road		Fax		Central (West of I-95 and East of I-77): Yes	
Tryon, NC 28782				Mountains (West of I-77): Yes	
	Webs	site <u>www.peakhydrogeologic.com</u>			
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ov	verfill Prevention Equipment Operability Che	eck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Sta	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Sp	ill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No US	ST Internal Inspections (Integrity Assessme	ents): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Ot	her:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental S	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No US	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes US	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes W	aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Ot	her:			
Soil and Water Testing Lab:	No				
Company		Listing Su	Ibmitted 5/2/2018	Area of state conducts work	
Petroleum Solutions Inc.	Ph	one (919) 605-1979		Coastal (East of I-95): Yes	
3012 Whitehart Ln.		Fax (919) 773-1704		Central (West of I-95 and East of I-77): Yes	
819 Purser Drive				Central (West of 1-33 and East of 1-77). 163	
		,			
Raleigh, NC 27606	Webs	•		Mountains (West of I-77): No	
		,			
-	oliance Testing	site www.petroleumsolutionsinc.net	eck: <u>Yes</u>	Mountains (West of I-77): No	No
Сотр	No Ov	site www.petroleumsolutionsinc.net and Monitoring	eck: <u>Yes</u> No	Mountains (West of I-77): No UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	No Ov Yes Sta	www.petroleumsolutionsinc.net and Monitoring verfill Prevention Equipment Operability Che		Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No Ov Yes Sta	and Monitoring verfill Prevention Equipment Operability Cheatistical Iventory Reconciliation Services:	No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Ov Yes Sta No Sp No Ta	and Monitoring verfill Prevention Equipment Operability Cheatistical Iventory Reconciliation Services: vill Prevention Equipment Testing:	No <u>Yes</u> No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Over Yes Start No Sport No Tail No US	and Monitoring verfill Prevention Equipment Operability Che atistical Iventory Reconciliation Services: vill Prevention Equipment Testing: nk Tightness Testing:	No <u>Yes</u> No	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No <u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Over Yes Strain No Sport No Tail No US	and Monitoring rerfill Prevention Equipment Operability Cheatistical Iventory Reconciliation Services: will Prevention Equipment Testing: which Tightness Testing: To Internal Inspections (Integrity Assessment)	No Yes No nts): No	Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Over Yes Strain No Sport No Tail No US	and Monitoring verfill Prevention Equipment Operability Cheatistical Iventory Reconciliation Services: will Prevention Equipment Testing: what Tightness Testing: The Internal Inspections (Integrity Assessments of Internal Lining Inspections:	No Yes No nts): No	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Over Section Ov	and Monitoring rerfill Prevention Equipment Operability Cheatistical Iventory Reconciliation Services: will Prevention Equipment Testing: Internal Inspections (Integrity Assessment Internal Lining Inspections: her:	No Yes No nts): No	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Over Space Testing No Over Space State State Space	and Monitoring rerfill Prevention Equipment Operability Cheatistical Iventory Reconciliation Services: will Prevention Equipment Testing: Internal Inspections (Integrity Assessment Internal Lining Inspections: her:	No Yes No nts): No	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Over Space Testing No Over Space Testing No Space Testing No Ta No US No US No Ot No Ot No Ot No US No Ot No US No Ot No US No US No Ot No US	and Monitoring verfill Prevention Equipment Operability Che atistical Iventory Reconciliation Services: will Prevention Equipment Testing: when Tightness Testing: To Internal Inspections (Integrity Assessment To Internal Lining Inspections: wher:	No Yes No No No	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Over Service Testing No Over Service Testing No Service Testing No US No US No Ot No Ot No US No Ot No US	and Monitoring verfill Prevention Equipment Operability Che atistical Iventory Reconciliation Services: sill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessmental Internal Lining Inspections: her: ervice Firms ST Compliance Consultants:	No Yes No No No	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Over Yes Standard No Over Yes Standard No Use No Ott No Ott No Use No	and Monitoring verfill Prevention Equipment Operability Che atistical Iventory Reconciliation Services: vill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessment ST Internal Lining Inspections: her: ervice Firms ST Compliance Consultants: ST Equipment Verification:	No Yes No No No No No Yes	Wountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes Yes Yes

Company		Listing Su	Ibmitted 5/22/2019	Area of state conducts work	
Petroleum Tec	P	hone (704) 804-1213		Coastal (East of I-95):	Yes
5420 Powerhouse Ct		Fax		Central (West of I-95 and East of I-77):	
Concord, NC 28027		I dx			
	Web	osite <u>www.petroleumtec.com</u>		Mountains (West of I-77):	res
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contract	ors
Automatic Line Leak Detector Testing:	No C	Overfill Prevention Equipment Operability Che	eck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	JST Internal Inspections (Integrity Assessmen	nts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No C	Other:	Tank Cleaning	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other: T	ank Cleaning
Emergency Cleanup - Spill/Release:	<u>Yes</u> U	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No U	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No V	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:	Tank Cleaning		
Soil and Water Testing Lab:	No				
Company		Listing Su	ibmitted 11/14/2018	Area of state conducts work	
PGP Services, LLC	P	hone (704) 619-1528		Coastal (East of I-95):	Yes
1949 Candlewick Drive		Fax (803) 802-2441		Central (West of I-95 and East of I-77):	Yes
Fort Mill, SC 29715		(000) 00= =			
					Vac
	Web	osite		Mountains (West of I-77):	Yes
Comp		osite g and Monitoring			
Comp Automatic Line Leak Detector Testing:	pliance Testing		eck: <u>Yes</u>	Mountains (West of I-77):	
_	pliance Testing	g and Monitoring	eck: <u>Yes</u> No	Mountains (West of I-77): UST Equipmment Service Contract	ors
Automatic Line Leak Detector Testing:	Yes S	g and Monitoring Overfill Prevention Equipment Operability Che		Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration:	ors No
Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes S Yes S	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	ors No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes S Yes S Yes S Yes S Yes S	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u> No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	ors No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes S Yes S Yes S Yes S Yes S Yes S	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S Yes S Yes T Yes T	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment	No Yes No nts): No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes S Yes S Yes S Yes T Yes U	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: JST Internal Inspections (Integrity Assessment JST Internal Lining Inspections:	No Yes No nts): No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No Yes Yes No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S Yes S Yes T Yes U	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	No Yes No nts): No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No Yes Yes No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S Yes S Yes S Yes S Yes S Yes C No C Yes	g and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	No Yes No nts): No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S Yes S Yes S Yes S Yes S Yes S Yes C Yes C Yes C Yes C No C Yes nvironmental S	g and Monitoring Described Prevention Equipment Operability Chestatistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment Internal Lining Inspections: Other: Service Firms	No Yes No No No	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Yes S No S No S Yes S No	g and Monitoring Description Equipment Operability Chestatistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Dether: Service Firms UST Compliance Consultants:	No Yes No No No Yes	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes S Yes S Yes S Yes S Yes S Yes C	g and Monitoring Diverfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Dither: Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes No No No Yes Yes Yes	Mountains (West of I-77): UST Equipmment Service Contract Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No Yes Yes No No No No No

UST Se	ervice P	rovider List (All) - Environment	al Service	e Firms Only	
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Pilot Geological, PLLC		Phone (336) 310-4527		Coastal (East of I-95): Yes	3
743 Park Lawn Court		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	6
PO 128		,		Mountains (West of I-77): Yes	
Kernersville, NC 27285	V	/ebsite www.pilotenviro.com		modificanto (vooc or 177). Too	,
Com	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/8/2019	Area of state conducts work	
Practical Environmental Solutions, PC		Phone (910) 790-8265		Coastal (East of I-95): Yes	3
5634 Harvest Grove Lane		Fax		Central (West of I-95 and East of I-77): Yes	;
Wilmington, NC 28409	\A	/ebsite www.oil-tank.com		Mountains (West of I-77): No	
-		ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
	NIO			UST System Removal:	<u>Yes</u>
Line Tightness Testing:	No			Othors	
E		al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	nvironmenta <u>Yes</u>	UST Compliance Consultants:	Yes	Other:	
E	nvironmenta		Yes No	Other:	

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

Oil Tank Evaluations

Other:

Waste Disposal and Treatment:

No

<u>Yes</u>

Company		Listing Submitted		Area of state conducts work	
Precision Tank Service	Ph	one (704) 892-8600		Coastal (East of I-95): Yes	
P.O. Box 2040		Fax (704) 892-8711		Central (West of I-95 and East of I-77): Yes	
20468 Chartwell Center Dr		(104) 092-0111			
Cornelius, NC 28031	Webs	site <u>precisiontankservice.com</u>		Mountains (West of I-77): Yes	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		verfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes St	atistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		oill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		ink Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes US	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u> Ot	her:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental S	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No US	ST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No US	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Ot	her:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	2/24/2020	Area of state conducts work	
Professional Service Industries, Inc.	Ph	one (704) 598-2234		Coastal (East of I-95): Yes	
5021 W W.T. Harris Blvd.		Fax (704) 598-2236		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28269		(101)		Mountains (West of I-77): Yes	
	Webs	site http://www.intertek.com/building		woultains (west of 1-77). Tes	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Sp	oill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:					No
	No Ta	ink Tightness Testing:	No	UST Equipment Installation - Other:	INO
Corrosion Protection System Testing:	No Ta	nk Tightness Testing: ST Internal Inspections (Integrity Assessments):		UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ta	ink Tightness Testing:	No	UST Equipment Repair: UST System Installation - Complete Systems:	
Corrosion Protection System Testing:	No Ta No US No US	nk Tightness Testing: ST Internal Inspections (Integrity Assessments):	No No	UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ta No US No US	ink Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No US No US No Ot	Ink Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No US No US No Ot No Ot No	Ink Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No US No US No Ot No No No No No No No No US	Ink Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her: ervice Firms	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Ta No US No Ot No Ot No No Ot No US No VS Ves US	Ink Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her: ervice Firms ST Compliance Consultants:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Ta No US No Ot No Ot No VS No VS Ves US Yes W	Ink Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her: ervice Firms ST Compliance Consultants: ST Equipment Verification:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No

Company		Listing Submitted	11/15/2018	Area of state conducts work	
Progress Environmental Group, Inc.	Phone	(336) 722-9999		Coastal (East of I-95): Yes	
120 Fayette Street	Fax	(336) 722-9998		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27101		(,		Mountains (West of I-77): Yes	
	Website	www.progressenvironmental.com		moditalits (West 61177). 163	
Comp	oliance Testing and	l Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill Pr	evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank T	ightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST In	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST In	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental Servi	ce Firms		Other:	
Emergency Cleanup - Spill/Release:		ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes Other:				
Soil and Water Testing Lab:	No				
		Listing Culturitted	44/45/0040	Avec of state conducts would	
Company		Listing Submitted	11/15/2018	Area of state conducts work	
Protective Technologies, Inc.	Phone	()		Coastal (East of I-95): Yes	
711 Mill Street Camden, SC 29020	Fax	(803) 424-0414		Central (West of I-95 and East of I-77): Yes	
Carridon, GO 20020	Website	www.protectivetechnologiesinc.com		Mountains (West of I-77): Yes	
Come		<u> </u>		LICT Equipment Comics Contractors	
	oliance Testing and		.,	UST Equipment Service Contractors	NI-
Automatic Line Leak Detector Testing:		Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:		evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
		ightness Testing:	No No	UST Equipment Installation - Other:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:		ternal Inspections (Integrity Assessments):	No	UST Equipment Repair: UST System Installation - Complete Systems:	No
Leak Detection Equipment Operability Check. Leak Detection Monitoring Services:		ternal Lining Inspections:	No	UST Piping/Sump Installation:	No
					No No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental Servi			Other:	
Emergency Cleanup - Spill/Release:		ompliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No UST Ed	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Waste	Disposal and Treatment:	No		
		Disposal and Treatment:	No		

Company		Listing Submitted	11/14/2018	Area of state conducts work	
Pyramid Environmental & Engineering PC	P	Phone (336) 335-3174		Coastal (East of I-95): Yes	
503 Industrial Ave		Fax (336) 691-0648		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27406		(666) 661 6616		Mountains (West of I-77): Yes	
	We	bsite <u>www.pyramidenvironmental.com</u>		would all s (West of 1-77). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No 7	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No l	JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No l	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes l	JST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes \	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/15/2018	Area of state conducts work	
RES, Inc	P	Phone (252) 809-3608		Coastal (East of I-95): Yes	
PO Bob 402		Fax		Central (West of I-95 and East of I-77): Yes	
3593 Wild Cat Road				Mountains (West of I-77): No	
Williamston, NC 27892	We	bsite		Widulitailis (West of 1-77). No	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:		Leak Detection Equipment Installation Servicing:	No
	110	Statistical iventory reconciliation Services.	No	Loak Dotockon Equipment motaliation Corvining.	
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No No	Spill Bucket Installation Repair:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S				No No
	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	
Corrosion Protection System Repairs:	No S No T No U	Spill Prevention Equipment Testing: Fank Tightness Testing:	No No	Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S No T No U	Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments):	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No T No U	Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No No No	Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No I	Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: Other:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No No No No No No No nvironmental Yes U	Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No S No N	Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: Other: Service Firms JST Compliance Consultants:	No No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S No N	Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No

UST Service Provider List (All) -	- Environmental	Service	Firms Only
	Listing Submitted	9/6/2018	Area of sta

Company		Listing Submitted	9/6/2018	Area of state conducts work	
SCS Engineers, PC	P	Phone (704) 504-3107		Coastal (East of I-95): Yes	
2520 Whitehall Park Drive, Suite 450		Fax		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28273				Mountains (West of I-77): Yes	
	We	bsite <u>www.scsengineers.com</u>		mountaine (Proceeding). 100	
Comp	pliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No l	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No l	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	·	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	· · · · · · · · · · · · · · · · · · ·	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/14/2018	Area of state conducts work	
SENSIBLE SOLUTIONS ENVIRONMENTAL	F	Phone (336) 263-0965		Coastal (East of I-95): No	
PO BOX 3074		Fax		Central (West of I-95 and East of I-77): Yes	
CHAPEL HILL, NC				Mountains (West of I-77): No	
	We	ebsite <u>www.sensible-solutions-environmental.c</u>	<u>com</u>	Mountains (West of 1-77). No	
Comp	pliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Operability Check:			NI-
Containment Sump Testing:		Overnii Frevention Equipment Operability Check.	No	Dispenser Meter Repair/Calibration:	No
		Statistical Iventory Reconciliation Services:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S				
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
	No S No S No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection System Repairs:	No S No S No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S No S No No N	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No S No No N	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No S	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Service Provider List (All) - Environmental S	Service	Firms Only
Listing Submitted 12	2/12/2019	Area of stat

Company		WIGOT Elot (7 till)	Listing Submitted		Area of state conducts work	
Shield Engineering, Inc.	P	hone (704) 394-6913	<u> </u>		Coastal (East of I-95): Yes	
4301 Taggart Creek Road		Fax (704) 394-6968			Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28208		1 dx (704) 394-0900				
	Web	osite www.shieldengine	eering.com		Mountains (West of I-77): Yes	
Comp	oliance Testing	g and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	Overfill Prevention Equipmer	nt Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconcilia	ation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment T	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	IST Internal Inspections (Int	tegrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	IST Internal Lining Inspection	ons:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No C	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironmental S	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u> U	IST Compliance Consultant	ts:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes U	IST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Vaste Disposal and Treatme		<u>Yes</u>		
Oil and Solvent Recycling:	No C	Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	11/14/2018	Area of state conducts work	
Singleton Environmental, Inc.	P	hone (828) 667-5001			Coastal (East of I-95): No	
PO Box 2012		Fax (828) 667-0105			Central (West of I-95 and East of I-77): No	
1301 Sand Hill Road		(020) 007 0100				
Enka, NC 28728						
I and the second	Wek	osite www.singletonen	vironmental.com		Mountains (West of I-77): Yes	
Comp		g and Monitoring	vironmental.com		Wountains (West of I-77): Yes UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	oliance Testing			No	. ,	No
_	pliance Testing	g and Monitoring	nt Operability Check:	No No	UST Equipmment Service Contractors	No No
Automatic Line Leak Detector Testing:	No C	g and Monitoring Overfill Prevention Equipmer	nt Operability Check: ation Services:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No S No S	g and Monitoring Overfill Prevention Equipmer statistical Iventory Reconcilia	nt Operability Check: ation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No C No S No S No T	g and Monitoring Overfill Prevention Equipment statistical Iventory Reconcilians in the provention Equipment To the provention Equipment Eq	nt Operability Check: ation Services: Testing:	No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No C No S No S No T No U	g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconcilia pill Prevention Equipment Tank Tightness Testing:	nt Operability Check: ation Services: Testing: tegrity Assessments):	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No CONO SONO TO NO UNO UNO UNO UNO UNO UNO UNO UNITERIOR DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DE LA CONTRACTION DE LA CONTRAC	g and Monitoring Overfill Prevention Equipment attaistical Iventory Reconcilians in the prevention Equipment To ank Tightness Testing: UST Internal Inspections (Internal Inspections)	nt Operability Check: ation Services: Testing: tegrity Assessments):	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No CONO SONO TO NO UNO UNO UNO UNO UNO UNO UNO UNITERIOR DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DE LA CONTRACTION DE LA CONTRAC	g and Monitoring Overfill Prevention Equipment Itatistical Iventory Reconciliately Prevention Equipment Trank Tightness Testing: IST Internal Inspections (Internal Lining Inspections)	nt Operability Check: ation Services: Testing: tegrity Assessments):	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No CONTROL	g and Monitoring Overfill Prevention Equipment attainstical Iventory Reconcilia spill Prevention Equipment Trank Tightness Testing: UST Internal Inspections (Internal Lining Inspection) Other:	nt Operability Check: ation Services: Testing: tegrity Assessments):	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No CON NO	g and Monitoring Overfill Prevention Equipment attainstical Iventory Reconcilia spill Prevention Equipment Trank Tightness Testing: UST Internal Inspections (Internal Lining Inspection) Other:	nt Operability Check: ation Services: Festing: tegrity Assessments): ons:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Convironmental Street	g and Monitoring Deerfill Prevention Equipment Italistical Iventory Reconcilia ipill Prevention Equipment Trank Tightness Testing: UST Internal Inspections (Internal Lining Inspection) Uther: Service Firms	nt Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Convironmental Street	g and Monitoring Deerfill Prevention Equipment Statistical Iventory Reconcilia Spill Prevention Equipment Teank Tightness Testing: UST Internal Inspections (Internal Lining Inspection) Other: Service Firms UST Compliance Consultants	nt Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Convironmental Stress U Yes W	g and Monitoring Described Service Firms UST Compliance Consultants UST Compliance Consultants UST Compliance Consultants UST Compliance Consultants UST Equipment Verification:	nt Operability Check: ation Services: Testing: tegrity Assessments): ons:	No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

USTS	ervice	Provide	er List (All) - I			e Firms Only	
Company				Listing Submitted	11/16/2018	Area of state conducts work	
SR&R Environmental, Inc.		Phone	(910) 763-6274			Coastal (East of I-95): Ye	S
4920 Highway 421 N.		Fax	(910) 763-6132			Central (West of I-95 and East of I-77): Ye	S
PO Box 221 Wilmington, NC 28402		Website	www.srrenviro.com		Mountains (West of I-77): Yes		
Comp	pliance 1	esting and	Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill F	Prevention Equipment O	perability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistica	al Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	vention Equipment Test	ng:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tig	ghtness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Inte	ernal Inspections (Integri	ty Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Inte	ernal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	No
Eı	nvironm	ental Servic	e Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Co	mpliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste D	Disposal and Treatment:		<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:		Vacuum Truck Se	ervices		
Soil and Water Testing Lab:	No						
Company				Listing Submitted	11/14/2018	Area of state conducts work	
Terracon Consultants, Inc.		Phone	(704) 509-1777			Coastal (East of I-95): Ye	S
2701 Westport Road Charlotte, NC 28208		Fax	(704) 509-1888			Central (West of I-95 and East of I-77): Ye	s
Onanoue, NO 20200		Website	www.terracon.com			Mountains (West of I-77): Ye	S
Comp	pliance 1	esting and	Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill F	Prevention Equipment O	perability Check:	No	Dispenser Meter Repair/Calibration:	No

Charlotte, NC 28208		() 555 1555			
		Website www.terracon.com		Mountains (West of I-77): Ye	es
Comp	UST Equipmment Service Contractors				
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironme	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				

Company			Listing Submitted	11/15/2018	Area of state conducts work	
Terraquest Environmental Consultants, P.C.		Phone	(919) 563-9091		Coastal (East of I-95): Yes	
100 E. Ruffin Street		Fax	(919) 563-9095		Central (West of I-95 and East of I-77): Yes	
Mebane, NC 27302			(6.5)		Mountains (West of I-77): Yes	
	W	Vebsite	www.terraquestpc.com		mountains (west of 1-77). Tes	
Comp	oliance Test	ting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill F	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tiç	ghtness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Inte	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Inte	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
En	nvironmenta	al Servic	e Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Co	mpliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Eq	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu			Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	11/20/2018	Area of state conducts work	
TideLand Construction, LLC		Phone	(252) 524-1644		Coastal (East of I-95): Yes	
3600 North Drive		Гои	(252) 565-8724		Central (West of I-95 and East of I-77): Yes	
Greenville, NC 27834-		Fax				
Oreenville, NO 27054		Fax	(232) 303 0724			
Greenvine, NO 27034	W	Vebsite	tidelandconstruction.com		Mountains (West of I-77): Yes	
	W oliance Test	Vebsite	tidelandconstruction.com			
		Vebsite ting and	tidelandconstruction.com	Yes	Mountains (West of I-77): Yes	<u>Yes</u>
Comp	oliance Test	Vebsite ting and Overfill F	tidelandconstruction.com Monitoring	Yes No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes Yes
Comp Automatic Line Leak Detector Testing:	oliance Test No	Vebsite ting and Overfill F	tidelandconstruction.com Monitoring Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No Yes	Vebsite ting and Overfill F Statistica Spill Pre	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Yes No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing:	No <u>Yes</u>	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Yes No No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte	Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	No <u>Yes</u> No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Yes No No No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No Yes No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No Yes	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No Yes No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte UST Inte Other:	Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No Yes No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte UST Inte Other:	Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No Yes No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No No No Yes No No No Yes No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte UST Inte Other:	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No Yes No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No Yes No No No Yes No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte UST Inte Other: UST Cot UST Cot UST Equ	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: The Firms mpliance Consultants:	No Yes No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes No No No Yes No	Vebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte UST Inte Other: UST Cot UST Cot UST Equ	Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: The Firms Impliance Consultants: uipment Verification:	No Yes No No No No Ves	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Company		Listing Submitted	d 8/12/2020	Area of state conducts work	
TIMMONS GROUP	Pl	hone (919) 866-4951		Coastal (East of I-95): Yes	
5410 TRINITY ROAD, SUITE 102		Fax		Central (West of I-95 and East of I-77): Yes	
RALEIGH, NC 27606				Mountains (West of I-77): Yes	
	Web	osite http://www.timmons.com/		mountains (vost of 177). Too	
Comp	pliance Testing	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No O	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmental S	Service Firms		Other: SYSTEM DESIGN SERVICES - UST ENGIN	EERING
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:		ST Equipment Verification:	No No		
Environmental Engineer/Geologist Soil and GW Cleanu	u No W	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:		other: SYSTEM DESIGN SERVICES - UST ENGIN	NEERING		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	d 5/22/2018	Area of state conducts work	
Vistabution LLC	PI	none (919) 844-9375		Coastal (East of I-95): Yes	
8315 Six Forks Rd		Fax (919) 861-0849		Central (West of I-95 and East of I-77): Yes	
Suite 205 Raleigh, NC 27615		,		Mountains (West of I-77): Yes	
Raleigh, NC 27013	Wak				
	wer	osite www.vistabution.com			
Com		g and Monitoring		UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	pliance Testing		No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
	pliance Testing	g and Monitoring	No No		
Automatic Line Leak Detector Testing:	pliance Testing No O No S	g and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No O No S No S	g and Monitoring Overfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No O No S No S No T	g and Monitoring Overfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No O No S No S No S No T No U	g and Monitoring Overfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No O No S No S No T No U No U	g and Monitoring Overfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Ipill Prevention Equipment Testing: In Tightness Testing: Ist Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No O No S No S No T No U No U	Diverfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No O No S No S No T No U No U No O	g and Monitoring Overfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Ipill Prevention Equipment Testing: In ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Ither:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No O No S No S No T No U No U No O No O	g and Monitoring Overfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Ipill Prevention Equipment Testing: In ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Ither:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No O No S No S No T No U No U No O No O No T No U No O No O No O No T No U No O	part of the control o	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No O No S No S No T No U No U No O No O No T S No U No U No O No O S T S T S T S T S T S T S T S T S T S	pand Monitoring Exercise Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Ipill Prevention Equipment Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspection	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No O No S No S No Ti No U No O No O No O No O No O No O Version S Ves U Yes W	g and Monitoring Diverfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other: Service Firms IST Compliance Consultants: IST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

UST Service Provider List (All) - Environmental Service Firms Only

Company		Listing Submitted	8/13/2020	Area of state conducts work	
WithersRavenel, Inc.	Phone	(919) 469-3340		Coastal (East of I-95): Yes	;
115 MacKenan Drive Cary, NC 27511	Fax	K.		Central (West of I-95 and East of I-77): Yes	;
Cary, NO 27511	Website	www.withersravenel.com		Mountains (West of I-77): Yes	i
Comp	liance Testing and	d Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Overfil	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Statist	ical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill P	revention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank 7	Fightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST Ir	nternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST Ir	nternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironmental Serv	ice Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes UST C	compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes UST E	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes Waste	Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Other:	Phas	e I ESAs		
Soil and Water Testing Lab:	No				